

# **finder** Cross Reference Guide by Series



Finder	30 Series	34 Series	36 Series	38 Series	40 Series	41 Series	43 Series	55 Series	56 Series	60 Series	62 Series
Allen-Bradley		700-TBR		700-HL	700-HP			700-HC	700-HF	700-HA	700-HB 700-HD
American Zettler	AZ820 AZ830		AZ941		AZ690 AZ692 AZ725 AZ735	AZ742 AZ762 AZ763 AZ764	AZ696	AZ140	AZ1309	AZ1010	
Aromat	DS2E DS2Y	APE	JS		JW JR			HC2 HC3 HC4	HL2		HP32 HP33
Carlo Gavazzi					MZF MZP		M15EB M15ED	RMI		RF11 RF80	
Cutler Hammer								D2PR	D7PR2 D7PR4	D3PR	D5PR
Deltrol								320	310	201	203
Eagle Signal								17P4		22Q	30E
Eichhoff	E230				E3201 E3206 E3208		E3207 E3242				
Elesta					SGR		SVR			SKR	
Feme					MZF MZP	M15MB	M15EB M15ED			RCP	
Fujitsu	FBR240		FBR160		FBR610 FBR620		JS	FRL263/02 FRL263/03 FRL263/04	FRL263/02 FRL263/04		FRL251 FRL253
Furnas								46PD	46PC	46PA	46B 46PB
Guardian	1495		1725		1625 1655 1665			1310 1315	1390 1395	1210 1410 1415	1510 1515
Hasco	HAS HS		KLT		PR				UJ		
IDEC	RD2N RW22		RCN1V					RY4S RU2S RU4S RM2	RH2B RH4B	RR2P RR3P	RR2B RR3B
Kuhnke	RE2L RG2L				107G1 107G2 107P1 109G1 109G2 109P1	171G1 171G2 171P1		111A4 111G4		UF2 UF3 RS	UB2 UB3 RS

Please validate cross by reviewing detailed technical specifications found in the Finder catalog.

9/17/2004 (IK)

# **finder** Cross Reference Guide by Series



Finder	30 Series	34 Series	36 Series	38 Series	40 Series	41 Series	43 Series	55 Series	56 Series	60 Series	62 Series
Magnecraft			W178		W76	W76		W78 782	W78AR W78RC 782	W250 750	W388
Midtex	190		296		409			156	258	155 158	157
NTE	R40		R46		R22 R25			R12	R14	R02	R10
Omron	G2V G5V2		G5LE		G2R	G2RL	G6RN	MY2 MY3 MY4	LY2 LY4	MK2P MK3P	MJ2P MJ3P
P&B / Tyco	V23105		T7C T7N T70		RKA RKS	RT	T75	KHU KHAU	K10P	KRPA	KUP
Phoenix		REL-MR		PLC-RSC	REL-KSR	REL-MR					
Relpol					RM82 RM83	RM84 RM85	RM96	R4		R15	
Schrack	RS		TN ZF		RP	RT	RY	RA ZG ZT	TM	MT MR MZ RL	RM
Siemens	V23105 V23024	V23092	V23082		V23037 V23056		V23061	V23100-V7		V23100-V9	
Sky	SKG		CKC		SKE			SKMP	SKNP	SKKP	SKAP
Song Chuan			801H		793	845		SCLB SCLD	SCL SCLA	703	731
Square D								8501RS	8501RS	8501KP	8501KF 8501KU
Struthers-Dunn	272		270		277			C281	C281	A314	A283
Takamisawa					VS		JS				
Turck/Releco								C9	C7	C2 C3	C5

**For assistance, alternative crosses and items not listed, please feel free to call us at 770-271-4431.**

## ***FINDER RELAYS, INC.***

4465 Commerce Drive, Suite 103  
Buford, GA 30518

Phone: **770-271-4431**

Fax: **770-271-7530**

For details on Relays, Timers and Sockets, please visit our Website at

**[www.findernet.com](http://www.findernet.com)**

Please validate cross by reviewing detailed technical specifications found in the Finder catalog.

9/17/2004 (IK)